

Snap
Light
for
XTeink
X4

MIKEL
SANTIAGO
EL MENTIROSO



Parts List


3D Printed Parts:

- (A) Top cover
- (B) LED Diffuser
- (C) Charger Board cover
- (D) Battery cover
- (E) Internal cover


Electronic Parts:

- (F) Battery
- (G) Charger Board
- (H) Cable Adapter
- (I) LED Board






1. Insert Charge Board (G) into its Charge Board Cover (C), following the side guides.




TOP VIEW
(F) BAT Connector
(H) LED Connector




BOTTOM VIEW
Charging Port
On/Off Switch




2. Place Battery (F) into its Cover (D)



3. Connect Battery (F) and Cable Adapter (H) to Charge Board (G)




4. Place Battery (F), Charge Board (G), and Cable Adapter (H) into Internal Cover (E). Guide cables as you insert each component



5. Slide each component until it's securely fitted




NOTE: Place the cables according to the reference image, to keep them contained within the Internal Cover. Remember that they are delicate cables and should be handled with caution.



6. Pass **Cable Adapter (H)** through the interior slot and extend it to the exterior





7. Connect **Cable Adapter (H)** with **LED Board (I)** and activate **on/off switch** of **Charge Board (G)** to check if it's working correctly



8. Insert **Internal Cover (E)** into **Top Cover (A)** with extreme care to avoid damaging **Cable Adapter (H)**





9. Insert the protruding part of **LED Diffuser (B)** into left slot of **Top Cover (A)**, as shown in the image



10. Insert **X4 reader** into **Top Cover (A)**

